


LED Light

INSTALLATION INSTRUCTIONS

1. Parts in Box



5. Tighten the clamps with a screw driver or socket wrench.



6. Trim away extra clamp strap material.



7. Place plastic clamp end piece over sharp end of clamp strap so there are no sharp edges.



2. Place 2-way tape on feet of bracket. This will reduce vibration and prevent rattling.

8. Plug in wire, wrap connection with electrical tape.



3. Place light near back of over head guard. Ensure the operator can exit and enter the seat without hitting head on light.

9. Wire into forklift as desired. Light can accept voltages from 9-64 VDC. Red-Positive. Black-Negative.



4. Place the two clamps around the over head guard and secure the LED Light feet.

10. Angle light to appropriate distance, 2-6 feet is suggested depending on your company preference. Tighten down adjusters.

