

PROFESSIONAL PHOTO ARCHIVES

Tinker Air Force Base
Oklahoma City, OK
GSA DOD

mrtink4.jpg



Tinker AFB installed over 300 custom workbenches in their Pneumatic & Hydraulic Repair facility.

mrtink2.jpg



Each repair tech has his/her own workstation with diagnostics. Open areas are positioned every few benches for additional work space.

mrtink5.jpg



Control panels are fitted under stationary riser shelves with access holes at the back (above), then are sealed off for a finished look.

mrtink1.jpg



Electronics were run in a channel between bench rows, which were then hidden behind custom "tent" tops (see photo to upper left).

mrtink3.jpg

