


ZONE ALERT



Zone ALERT is a warning device to ALERT workers and other forklift operators that an area is occupied. It has the ability to count forklifts in and out of an area and keeps the alarms triggered until the last forklift has left.

- An occupancy zone warning device,
- Excellent for a one entrance / exit area
- Perfect for a refrigerator, cooler, freezer, narrow aisle or tunnel
- Warns that the area is occupied
- Counts vehicles in / out
- Strobes stay on until last vehicle exits

Zone ALERT



Note: 4 strobe lights shown.
Standard system includes 1 strobe light.