## AC 115V SG30 STOP & GO WIRING DIAGRAM (WITHOUT SWITCH-FOR EXTERNALLY CONTROLLED CIRCUITS)

